

ANL LCLS QA Presentation 2/27/07

(This presentation can be viewed at http://www.lcls.aps.anl.gov/Project_Page/QA/QA%20Presentations.html)

Quality Requirements for Procurement of items going to SLAC:

- 1. Obtain QA (Tom Barsz) review for ALL PARIS Requisitions PRIOR to routing the PARIS requisition or Service Request for approval. (Hard to add Quality requirements once the requisition is routed. QA approval will be much faster if the QA issues are addressed first.)**
 - ◆ **Tom's office is in Building 401, B4219.**
 - ◆ **Tom's email is tbarsz@aps.anl.gov**
 - ◆ **Tom's phone is 9177, pager: 4-9097, cell: 815-210-3107.**
- 2. Provide applicable APS drawings, Statement of Work, and Vendor names for QA review.**
- 3. Be prepared to discuss vendor quality assurance programs and inspection requirements, i.e., Will inspection required? Who is going to do the inspection? How will the inspection be documented?**
- 4. All drawings must be in Pro Intralink at the approved release level for any hardware being delivered to SLAC**